## **Simplified Tensile Tester**

PT-3000DG-P

## Grasping the weld strength and meeting the requirements are essential when high welding quality is demanded!

Are you sure your weld is strong enough? How can you explain how good your weld is?-----This Simplified Tensile Tester can be your solution.

Printer attached.



Place a spotwelded sample on the machine.



Pull it until the welded surface comes apart.





The shear strength is shown as a numeral. Press the print button to print the result.



Print out the result.







簡易引張試験機

PT-3000DG-P

Model	PT-3000-DG-P
Max. Measuring capacity	30kN(Measurable range: 2kN to 30kN)
Accuracy	±10%
Load indication	Digital
Clamping method	Top/Bottomclamps
Pressing method:	Manual Lever (With hydraulic jack)
Test Sample dimensions:	JIS 3136 for single point (30mmx100mm)
Weight:	82kg
Dimensions:	H800xW460xD400mm, desktop